



VIN NUMBER:



Meets ASE Standards



May Need Future Attention

Certification #: 6330-10009

N/A Not Applicable

Various Functions - Continued

Rear window defrost	<input type="checkbox"/>	N/A
Re-circulating Radio: AM	<input type="checkbox"/>	N/A
FM	<input type="checkbox"/>	N/A
Speakers	<input type="checkbox"/>	N/A
Cassette/ Disc Electrical:	<input type="checkbox"/>	N/A
Vanity Visor	<input type="checkbox"/>	N/A
Map/ Interior Turn signals	<input type="checkbox"/>	N/A
hazard flasher	<input type="checkbox"/>	N/A
Parking/ side marker	<input type="checkbox"/>	N/A
Brake lights	<input type="checkbox"/>	N/A
Back-up lights	<input type="checkbox"/>	N/A
Plate light	<input type="checkbox"/>	N/A
Dash & Console	<input type="checkbox"/>	N/A
Seat Heaters	<input type="checkbox"/>	N/A
Power Windows	<input type="checkbox"/>	N/A
Cigarette lighter	<input type="checkbox"/>	N/A

Operating Performance

Engine:	<input type="checkbox"/>	N/A
Starting	<input type="checkbox"/>	N/A
Idle smoothness	<input type="checkbox"/>	N/A
Acceleration	<input type="checkbox"/>	N/A
Transmission Shift	<input type="checkbox"/>	N/A
Manual/ Auto	<input type="checkbox"/>	N/A
Cruise control works	<input type="checkbox"/>	N/A
Noise:	<input type="checkbox"/>	N/A
Wind	<input type="checkbox"/>	N/A
Rattles	<input type="checkbox"/>	N/A
Vehicle Handling:	<input type="checkbox"/>	N/A
Vibration	<input type="checkbox"/>	N/A
Stability	<input type="checkbox"/>	N/A
Braking	<input type="checkbox"/>	N/A
ABS	<input type="checkbox"/>	N/A
Steering - Pulls	<input type="checkbox"/>	N/A
Left	<input type="checkbox"/>	N/A
Right	<input type="checkbox"/>	N/A

REV #2 - 11/2007

TIRE INSPECTION: TIRE TREAD DEPTH of 4/32 in. (minimum 3mm measured from the TOP of wear indicators) & Sidewall Inspection)

LOCATION	Inside	Center	Outside	Size/Brand & Condition
Left Front	6/32 mm	6/32 mm	6/32 mm	185/65/15 Futura
Left Rear	4/32 mm	4/32 mm	4/32 mm	185/65/15 Futura
Spare	6/32 mm	6/32 mm	6/32 mm	185/70/15 Speed Year
Right Rear	7/32 mm	7/32 mm	7/32 mm	185/65/15 Futura
Right Front	7/32 mm	7/32 mm	7/32 mm	185/65/15 Futura

Tire Pressure: 32

Wheels: Good

Location	Pad Measurement	Disc Condition	Comments
Left Front	60/6 mm	930 mm	Futura
Left Rear	80/6 mm	9080 mm	Futura
Right Rear	80/6 mm	9020 mm	Futura
Right Front	60/6 mm	932 mm	Futura

BRAKE INSPECTION: Brake pads (minimum 5mm) & Disc Inspection

Name of Technician: Brian Dixon

Name of Manager:

Managers Signature

Name of Store:

Store Number:

ADDITIONAL COMMENTS: Valve cover gasket is leaking. Air filter is dirty. Reconnect plugs and wires and do a 3-step fuel injection service. Both front and rear sway bar end links are loose.



THANK YOU!